








SmartCAM ARM X1

Diagramma di carico
Load Diagram

Heavy Spring ●
Lite Spring ○



F [kg]